Approved For Release 2002/08/28: CIA-RDP78B04747A000200030021-4

17 September 1971

| | - |
|---|--|
| MEMORANDUM FOR: Chief, SC&PB/SS | The same of the sa |
| SUBJECT : Claims for Lost Time Reimbursement REFERENCE : Your memo dated 15 September 2000 1 | 25X1A |
| REFERENCE: Your memo dated 15 September, same subject | |
| | |
| 1. Per paragraph #3 of referenced memo the following remare directed toward claims as outlined in your attachments. | 25X1A |
| 2. April 29 to May 12 for which 268 hours of lost time a 49 days of per diem are claimed as a result of complications in grouting the dash pots. It is understood that the dash pots constituted a change to the original configuration and installation and resultant complications do not seem surprising. It is belief that some room for negotiation should be found in this particular claim. | n- n |
| 3. For the period June 9 to June 15, 72 hours of lost ti | ine |
| and 13 days of per diem were claimed. It is necessary here to understand the arrangement under which the work was to be perfor | |
| provided one expert on a sub-contract | • |
| who was to use the GSA "bull gang" to accome | lish 25X1A |
| working around their extremely delicate machine. Since only one | 25X1A |
| man remained provided the only assistance available; the significant fact being that this was brought about at the insist Furthermore, it is understood that this "close the room effort only took like the room of the control of the | 25X1A |
| effort only took 1 1/2 days. | 25X1A |
| 4. As for the period July 6 through July 17 when the env mental conditions were in a state of flux and the question of hu and resultant damage to the machine was surfaced, the undersigned no comment. However, at some period prior to August 9, tech were dissatisfied with the large flow of air which was directed the so called "Punkas" and are resulted air which was directed | midity d has nicians |
| the so called "Punkas" and are reported to have made adjustments this air flow. It is believed that duct dampers were modulated manually to reduce this flow. Although it cannot be definitely that this action caused it, it is a fact that the temperature confor one of the two reheaters did burn out which subsequently conto a "no control" condition. | to ZONIA |
| 29 which is apparently 387 hours plus 61 days is claimed to be a | |
| | |

Approved For Release 2002/08/28 : CIA-RDP78B04747A000200030021-4

| of room environment not meeting specifithe most significant contributory reast referred to above. Also, the men from something during this time, although tout that he has no knowledge of what tisince they were working on a very compithe writer's field of expertise. It defforts were not a total waste of time quite busy. | on is the "no control" condition were certainly doing he writer is careful to point hey are able to accomplish lex device which is far beyond oes seem likely that their | 25X1A |
|--|--|-------|
| 5. It does seem reasonable to compensation for legitimate lost time. It is believed that there is room for as a result of the requirements levied various parties concerned. | can be negotiated with negotiation on both sides | 25X1A |
| | | 25X1A |
| Distribution: Orig & 1 2 - NPIC/SS/LB | | |

(9/17/71)

25X1A

25X1A

NPIC/SS/LB/E&MS